

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2020

Submitted Date:

03/06/2020

Document Number:

700400357

## FIELD INSPECTION FORM

 Loc ID 315620 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 3975  
 Name of Operator: ARGALI EXPLORATION COMPANY  
 Address: PO BOX 416  
 City: RANGELY State: CO Zip: 81648
**Findings:**

- 7 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rector, Jeff		jbrduco@yahoo.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
Rector, Brian		brector1983@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231172	WELL	PR	03/18/1985	GW	103-08841	FEDERAL I-2-3-101	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 3-6-2020 at approximately 14:00, inspector Rick Moran, conducted a follow up inspection at Argali Exploration well Federal I-2-3-101 in Rio Blanco county of FIR documents:

- 1) 679704833 dated 7-23-2019.
- 2) 679706054 dated 11-12-2019.
- 3) 679706675 dated 12-23-2019.

The following compliance issues are uncompleted:

- 1) Well head sign. Photo 2. Complete by 9-20-2019.
- 2) Lease road sign lying on ground. Photo 3. Complete by 1-25-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400357.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	No sign present at well head.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	09/20/2019
Type	OTHER		
Comment:	Lease road sign lying on ground.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	01/25/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 231172 Type: WELL API Number: 103-08841 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: \_\_\_\_\_                      Pit ID: \_\_\_\_\_                      Lat: \_\_\_\_\_                      Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment: Meter building pit.

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Blowdown                      Lined: \_\_\_\_\_                      Pit ID: \_\_\_\_\_                      Lat: \_\_\_\_\_                      Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment: Separator pit.

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective Action		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700400358	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088381">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088381</a>