

Inspection Photos

API: 061-06365

Operator: STRACHAN EXPLORATION

Inspection Date: 3/6/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 1. Facing south at the beginning of the access road. The road is graveled and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 2. Facing southwest along the road. The road has been built up and graveled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 3. Facing south along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 4. The cattle guard has been cleaned out of sediment and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 5. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 6. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 7. Facing toward the well site. Sign is posted on the fence. There was no sign of oil stained soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 8. Facing toward the tank battery. Berms are maintained around tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 9. The shed is maintained and no sign of oil stained soil was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 10. Facing northeast at the location. The unused equipment has been removed. This area will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 11. The cement pad remains at the northeast side of the location. This is considered unused equipment and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 12. Facing back southwest toward the location. The cement pad needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020

Inspection Photos



Photo 13. Facing southwest toward the tank battery and well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06365 | Date: 3/6/2020