

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2020

Submitted Date:

03/04/2020

Document Number:

688307127

**FIELD INSPECTION FORM**

Loc ID 317121 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 94300  
Name of Operator: WARD & SON\* ALFRED  
Address: P O BOX 737  
City: OGALLALLA State: NE Zip: 69153

**Findings:**

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	
Young, Rob		rob.young@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236505	WELL	PR	12/01/2019	OW	121-08995	BLOMENKAMP 2	PR

**General Comment:**

Reinspection, a berm/ditch was installed at the foot of the NE corner of the NE pit to limit sediment transport, still salt kill in the pasture below the pit (see attached photos)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Update labels 300 bbl AST, Adams County AIRS permit and crude oil, fiberglass produced water tank has no labels		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/06/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 308-280-0100

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment:	electric, motor was running	Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	same earth berms as 300 bbl AST produced water tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Location Construction**

Location ID: 236505 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 236505 Type: WELL API Number: 121-08995 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. Dec 2019 production reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water                  Lined: NO                  Pit ID:                  Lat:                  Long:

Reference Point: \_\_\_\_\_                  Other: \_\_\_\_\_                  Length: \_\_\_\_\_                  Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                  Liner Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock                  Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                  Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                  Oil Accumulation: NO                  2+ feet Freeboard: YES

Comment: NW pit

Corrective Action:

Date: \_\_\_\_\_

Type: Produced Water                  Lined: NO                  Pit ID:                  Lat:                  Long:

Reference Point: \_\_\_\_\_                  Other: \_\_\_\_\_                  Length: \_\_\_\_\_                  Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                  Liner Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock                  Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                  Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<input style="width:100%;" type="text"/>	
Corrective		Date:
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: _____
	Lat: _____	Long: _____
Reference Point: _____	Other: _____	Length: _____
		Width: _____
<b>Lining:</b>		
Liner Type:	Liner Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective		Date:
<b>Fencing:</b>		
Fencing Type: <u>Livestock</u>	Fencing Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective		Date:
<b>Netting:</b>		
Netting Type:	Netting Condition:	
Comment:	<input style="width:100%;" type="text"/>	
Corrective		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<u>NE pit, sediment from berms in pasture below pit/salt kill, dry</u> <u>No pit permits associated with 121-08995 nor 121-05528</u>	
Corrective		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402332836	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085934">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085934</a>
688307160	Ward & Son Alfred Blomenkamp 2A	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085918">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5085918</a>