

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/11/2020

Submitted Date:

03/11/2020

Document Number:

696301556

FIELD INSPECTION FORM

Loc ID: 459884 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Operator Information:
 OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459882	WELL	PR	01/09/2020	OW	123-49089	ANTELOPE FEDERAL O34-K31-20HNB	PR
459883	WELL	PR	01/11/2020	OW	123-49090	ANTELOPE FEDERAL 44-20-17XRLNC	PR
459885	WELL	PR	01/09/2020	OW	123-49091	ANTELOPE FEDERAL 34-20-17XRLNC	PR
459886	WELL	PR	01/09/2020	OW	123-49092	ANTELOPE FEDERAL T-20-17XRLNC	PR
459887	WELL	PR	01/09/2020	OW	123-49093	ANTELOPE FEDERAL T44-P41-20HNB	PR
459888	WELL	PR	01/09/2020	OW	123-49094	ANTELOPE FEDERAL T34-20-17XRLNB	PR
459889	WELL	PR	01/14/2020	OW	123-49095	ANTELOPE FEDERAL Y44-U41-20HNB	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash along the East and North sides of Location. See Photos		
Corrective Action:	Comply with Rule 603.f.		Date: 04/10/2020

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Line Heater		
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		40.379460,-104.345930
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	459882	Type:	WELL	API Number:	123-49089	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459883	Type:	WELL	API Number:	123-49090	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459885	Type:	WELL	API Number:	123-49091	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459886	Type:	WELL	API Number:	123-49092	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459887	Type:	WELL	API Number:	123-49093	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459888	Type:	WELL	API Number:	123-49094	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	459889	Type:	WELL	API Number:	123-49095	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Trast along the East and North sides of Location.	petrie	03/11/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301557	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5092299