

Inspection Photos
Operator: BP America
API#: 067-05139
Date: 3/10/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing northwestward. Revegetation is progressing largely with western wheatgrass and rubber rabbitbrush.



Photo 3. View of dense musk thistle rosettes within the project area.



Photo 4. View of berm along the southern edge of the working area that remains unstabilized.



Photo 5. View of reference area vegetation comprised of pinyon juniper woodland, with shrubby understory comprised of sagebrush and mountain mahogany.