

Inspection Photos  
Operator: BP America  
API#: 067-07843  
Date: 3/10/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing largely with western wheatgrass, crested wheatgrass, and rubber rabbitbrush.





Photo 3. View of cobble placed on southwestern cut-slope, providing partial stabilization.





Photo 4. View of unprotected soils within the southwestern cut-slope still needing stabilization.





Photo 5. View of reference area vegetation comprised of pinyon juniper woodland, with shrubby understory dominated by black sagebrush and mountain mahogany.