

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2020

Submitted Date:

03/06/2020

Document Number:

700400357

FIELD INSPECTION FORMLoc ID 315620 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 3975

Name of Operator: ARGALI EXPLORATION COMPANY

Address: PO BOX 416

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rector, Brian		brector1983@gmail.com	
, Argali Exploration Company	970-629-1906	argaliexplorationcompany@gmail.com	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Rector, Jeff		jbrduco@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231172	WELL	PR	03/18/1985	GW	103-08841	FEDERAL I-2-3-101	PR

General Comment:

COGCC Inspection Report Summary.

On 3-6-2020 at approximately 14:00, inspector Rick Moran, conducted a follow up inspection at Argali Exploration well Federal I-2-3-101 in Rio Blanco county of FIR documents:

- 1) 679704833 dated 7-23-2019.
- 2) 679706054 dated 11-12-2019.
- 3) 679706675 dated 12-23-2019.

The following compliance issues are uncompleted:

- 1) Well head sign. Photo 2. Complete by 9-20-2019.
- 2) Lease road sign lying on ground. Photo 3. Complete by 1-25-2020.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400357.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No sign present at well head.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	09/20/2019
Type	OTHER		
Comment:	Lease road sign lying on ground.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	01/25/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities				
Facility ID: 231172	Type: WELL	API Number: 103-08841	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: ☐Pit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Meter building pit.Corrective Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date: Anchor Trench Present: ☐Oil Accumulation: NO2+ feet Freeboard: YESComment: Corrective Date: Type: BlowdownLined: ☐Pit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Separator pit.Corrective Date: **Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment: Corrective Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Date:

Inspector Name: Moran, Rick

Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		
Corrective		
		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402335667	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088396
700400358	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5088381