

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402277904

Date Received:

01/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

| Contact Name | Phone | Email                                      |
|--------------|-------|--|
| Beebe, Sabre |       | SanJuanCOGCC@bp.com<br>sabre.beebe@bpx.com |

COGCC INSPECTION SUMMARY:

FIR Document Number: 693900719  
Inspection Date: 08/21/2019 FIR Submit Date: 08/28/2019 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325654

Location Name: EVELYN PAYNE GAS UNIT A- N35N6W Number: 32SENW County: LA PLATA  
Qtrqtr: SENW Sec: 32 Twp: 35N Range: 6W Meridian: N  
Latitude: 37.261418 Longitude: -107.554834

FACILITY - API Number: 05-067- -00 Facility ID: 215173

Facility Name: EVELYN PAYNE A Number: 1  
Qtrqtr: SENW Sec: 32 Twp: 35N Range: 6W Meridian: N  
Latitude: 37.261418 Longitude: -107.554834

CORRECTIVE ACTIIONS:

1  CA# 129763

Corrective Action: Revegetation is needed within the eastern and southwestern project area. This should be installed along with adequate stormwater controls to stabilize erosion within the project area.

Date: 10/31/2019

Response: CA COMPLETED Date of Completion: 09/26/2019

Operator Comment: reseeding performed 9/26/2019

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**2**  CA# 129764

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the project area. Stormwater controls need to be selected, installed, and maintained using good engineering practices such as those described in CDOT manuals for erosion control. This is the second corrective action for stormwater erosion at this location. Corective action is back-dated to document date non-compliance was first observed.

Date: 09/25/2018

Response: CA COMPLETED

Date of Completion: 09/26/2019

Operator Comment: Diversion ditch installed to direct storm water into the armored run down that was installed to direct stormwater preventing future cutting and to reduce velocity and prevent silt travel off pad. See attached.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 1/6/2020 11:53:19 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>       |
|------------------------|--------------------------|
| 402277904              | FIR RESOLUTION SUBMITTED |
| 402277915              | Work completed document  |

Total Attach: 2 Files