

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2020

Submitted Date:

03/10/2020

Document Number:

688000394

FIELD INSPECTION FORMLoc ID 317096 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kerr, Scott		scottk@kirkwoodcompanies.com	
Weinert, Dave	(307) 577-5329	davew@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117702	PIT	AC			-	RUDNIK 33-27	EI

General Comment:

Routine environmental inspection. Rem #7897 remains open and will require a supplemental eForm 27 requesting NFA status for closure. There are indications of a recent spill associated with the injection shed that require explanation and a Form 19 if the spill was 5 bbl of fluid or more.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: See attached photographs. The presence of a drainage trench, heavy equipment scrape marks on the inside face of the containment berm and residual surface area of wet soil within and north of the injection shed and around the concrete vault indicate this was likely a reportable spill.

Corrective Action: Provide a FIRR detailing what the above noted impacts were caused by (providing documentation that the release was less than 5bbbl) or submit a Form 19.

Date: 03/27/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Rem #7987 remains open. The last communication in the well file indicated Wesco would be submitting laboratory analytical data to COGCC.

Corrective Action: Submit the laboratory analytical data and the requested sample location drawing on a supplemental Form 27.

Date: 03/27/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402338844	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5091611
688000395	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5091596