

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/12/2020

Submitted Date:

03/12/2020

Document Number:

696301565

FIELD INSPECTION FORM

Loc ID 432677 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
 Address: 410 17TH STREET SUITE #1400
 City: DENVER State: CO Zip: 80202

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------|---------------------------------|
| , | | EHSRC@bonanzacrk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 432676 | WELL | PR | 10/14/2013 | OW | 123-37227 | State Antelope U-Y-32HNB | PR |
| 432754 | WELL | PR | 11/01/2019 | OW | 123-37267 | State Antelope P-T-32HNB | PR |
| 436243 | WELL | PR | 05/31/2018 | OW | 123-39003 | STATE ANTELOPE P41-T44-32HNC | PR |
| 436244 | WELL | PR | 07/21/2014 | OW | 123-39004 | State Antelope 41-44-32HNB | PR |
| 436826 | WELL | PR | 10/24/2014 | OW | 123-39279 | STATE ANTELOPE U41-Y44-32HNC | PR |

General Comment:

| Location | | | |
|--|--|--------|-------------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: _____ |
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained Soil at Wellheads, see photos | | |
| Corrective Action: | For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e." | | Date: <u>03/27/2020</u> |
| Type | STORAGE OF SUPL | | |
| Comment: | Unmarked Riser at Pumping Unit, see photos | | |
| Corrective Action: | Comply with Rule 603.f. | | Date: <u>03/17/2020</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Pump Jack | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 5 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|-----------------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>432676</u> | Type: | <u>WELL</u> | API Number: | <u>123-37227</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>PR</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>432754</u> | Type: | <u>WELL</u> | API Number: | <u>123-37267</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>PR</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>436243</u> | Type: | <u>WELL</u> | API Number: | <u>123-39003</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>PR</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>436244</u> | Type: | <u>WELL</u> | API Number: | <u>123-39004</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>PR</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| Facility ID: | <u>436826</u> | Type: | <u>WELL</u> | API Number: | <u>123-39279</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>PR</u> | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| Routine Field Inspection. Stained Soil at Wellheads and unmarked riser at Pumping Unit. | petrie | 03/12/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402341107 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094320 |
| 696301566 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5094309 |