

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2020

Submitted Date:

03/19/2020

Document Number:

700400532

**FIELD INSPECTION FORM**

Loc ID 315053 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment |
|-----------------|--------------|----------------------------|---------|
| Freeman, Kris   | 254-717-0435 | kfreeman@31operating.com   |         |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 230174      | WELL | PR     | 11/08/2000  | GW         | 103-07833 | FEDERAL 4-22  | PR          |

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 3-18-2020 at approximately 12:15, inspector Rick Moran, conducted a routine inspection at Lasso Oil & Gas well Federal 4-22 in Rio Blanco county.

The following compliance issues were observed:  
1) Container without label and secondary containment. Photo 4. Complete by 5-18-2020.

A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 700400532.

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | CONTAINERS  |       |            |
| Comment:           | Metal container without a label & secondary containment.<br>Container is empty. |       |            |
| Corrective Action: | Install sign to comply with Rule 210.d.   | Date: | 05/18/2020 |
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | WELLHEAD  |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |

Emergency Contact Number:

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 | Date: |  |
| Corrective Action: |     | Date: |  |

Overall Good:

**Spills:**

| Type   | Area | Volume |  |  |
|--|------|--------|--|--|
| In Containment:  | No   |        |  |  |
| Comment:   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

**Fencing/:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Type               | PIT |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Equipment:**

| Type: Deadman # & Marked          | #   |       | corrective date |
|-----------------------------------|-----|-------|-----------------|
|                                   | # 3 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Plunger Lift                | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

|                     |     |       |  |
|---------------------|-----|-------|--|
| Type: Gas Meter Run | # 1 |       |  |
| Comment:            |     |       |  |
| Corrective Action:  |     | Date: |  |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 230174 Type: WELL API Number: 103-07833 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 |                         |                       | Material Handling And Spill Prevention | Fail                     |         |

Comment: No secondary containment under metal container.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/18/2020

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh                      Netting Condition: Good

Comment: \_\_\_\_\_

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700400533    | inspection photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100763</a> |