

Inspection Photos
Operator: BP America
API#: 067-07037
Date: 3/16/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area. Vegetation is weedy. Weed debris needs to be removed and managed.



Photo 3. View of the western project area from the southwestern corner facing northward. Revegetation is progressing here with western wheatgrass, smooth brome, and sand dropseed.



Photo 4. View of pipe debris and stained soils at the wellhead.



Photo 5. View of the reference area, comprised of open pinyon-juniper woodland with sagebrush and herbaceous understory.