

# Inspection Photos

API: 071-08351

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 1.** Facing southwest along the access road near the GE 31-04 site. There are vehicle ruts along the road. The road needs to be graded and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 2.** Facing west along the access road. There is a large rock in the road and deep vehicle ruts along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 3.** The culvert inlet shown at red arrow is filled in with sediment causing stormwater to flow across the road causing erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 5.** The pipe risers have been LO/TO.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020

## Inspection Photos



**Photo 6.** The oil in the engine skid has been cleaned up. There is still some spotting stained soil around engine skid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08351 | Date: 3/19/2020