

Inspection Photos

API: 071-09238

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing southeast along the main lease road ascending the hill. There are vehicle ruts along the road. The road needs to be graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 2. The culvert along the main lease road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 4. The exhaust pipe is laying on the ground and pipe h braces guards are laying in the grass. Unused equipment needs to be used or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 5. The is oily water in the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 6. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020

Inspection Photos



Photo 7. There is oily waste in the engine skid at compressor.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09238 | Date: 3/19/2020