

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2020

Submitted Date:

03/20/2020

Document Number:

689901939

**FIELD INSPECTION FORM**

Loc ID 309235 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		ronaldmack@tcenergyllc.com	
Fitzgerald, Edie		ediefitzgerald@tcenergyllc.com	
Dylan Thomsen		timothy.thomsen@state.co.us	
BAKER DAVID		dbaker@auroramp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290523	WELL	PR	10/31/2007	GW	071-09279	GOLDEN EAGLE 31-6	RI

**General Comment:**

This is a location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location****Lease Road:**

Type	Main		
comment:	The main lease road on top of the ridge down to Cherry Canyon has recently been graded and maintained.		
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type			
Comment:	Good		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:			Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Fail			

**Comment:** There is erosion occurring along the access road where stormwater has flowed across the road creating a deep channel. There is also other areas along the access road where erosion is occurring down and on the side of the road. There are culverts filled in with sediment and stormwater is not properly diverted to the culverts. Areas of erosion will need to be repaired and stabilized. BMP's must be implemented in accordance with good engineering practice and must be maintained.  
There is oil stained soil around the engine skid that needs to be cleaned up. Operator must perform maintenance of equipment to prevent leaks.

**Corrective Action:** Install or repair required BMPs per Rule 1002.f.(2)C  
Implement or modify BMPs for improved material handling and spill prevention.  
Immediately clean up area.

Date: 04/17/2020

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	292682	2059195	
	292682	2059195	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901940	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101254">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101254</a>