

Inspection Photos

Operator: Hilcorp Energy
API#: 067-08158
Date: 3/18/2020



Photo 1. View of the project area from the northwestern corner entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here, largely with smooth brome.



Photo 3. View of area near well pad entrance where stormwater run-on is eroding down-slope toward the access road. Stabilization measures are needed here.



Photo 4. View of the southwestern edge of the well pad working area facing westward from the well pad entrance. Berms and eroding slopes need stabilization.



Photo 5. View of the surrounding reference area comprised of smooth brome dominated grass field.