

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/16/2020

Submitted Date:

03/16/2020

Document Number:

699500973**FIELD INSPECTION FORM**Loc ID 320165 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|--------------|--------------------------------|--------------------|
| Lloyd, Bill | | blloyd@petrosharecorp.com | Operations Manager |
| Brown, Devin | | dbrown@petrosharecorp.com | |
| Leonard, Mike | | mike.leonard@state.co.us | |
| Kirschner, Steven | | steven.kirschner@state.co.us | |
| Grimes, Meghan | 720-256-8774 | mgrimes@petrosharecorp.co m | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 202870 | WELL | PR | 09/01/2019 | GW | 001-08275 | MARLATT 1 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Pump jack on location is unused. see pic 2 | | |
| Corrective Action: | Comply with 603 f. | Date: | 06/16/2020 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

| | | | |
|-----------------------------------|-----------|-------|--|
| Type: Prime Mover | # 1 | | |
| Comment: | gas motor | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|----------|---|----------|------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
|----------|---|----------|------|---------|--------|--|

| | | | | | | |
|--------------------|---|----------|-----------|--|---|-------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | | | Date: |

| | | | | | |
|--------------------|---|----------|----------------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | |
| | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | shares containment with oil tank | | | |
| Corrective Action: | | | | |
| | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | |
| | | | Date: |

| | | | | |
|----------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 202870 | Type: WELL | API Number: 001-08275 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR | | | |
| Corrective Action: | | | | Date: |

| | | | | |
|--|--|--|--|--|
| | | | | |
|--|--|--|--|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On 3/16/20 at approximately 1430 I, Inspector Justin Medina conducted an on-site inspection at Petroshare- API 001-08275 Marlatt 1 in Adams County Colorado.</p> <p>While there, I observed Shut in well</p> <p>This is a follow up inspection from document # 696900025</p> <p>Corrective actions from previous inspection appear to have been addressed.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Pump jack on location is unused. see pic 2</p> <p>Comply with 603 f. 6/16/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>At time of inspection perception of location may have been distorted due to weather conditions.</p> <p>This is a summary of inspection report.</p> | medinaj | 03/16/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402345866 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098878 |
| 699500974 | pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098870 |