

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #0817 from entrance to location



Photo #0825 Access road has not been maintained.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #0818 Debris around equipment.



Photo #0819 Debris around equipment.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #0823 Debris inside pit.



Photo #0821 Multiple places with unused equipment on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #0822 Multiple places with unused equipment on location.



Photo #0820 Flow line risers not LO/TO.