

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #0828 from entrance to location



Photo #0826 Access road has not been maintained.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #0827 Access road has not been maintained.



Photo #0833 Battery sign not posted.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #0831 Debris around equipment.



Photo #0832 Debris around equipment.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #0829 Debris inside pit.



Photo #0834 Tank containment berm needs repaired.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID: 312513



Photo #0830 Hole in wildlife protection device.