

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

699800786

FIELD INSPECTION FORMLoc ID 312507 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Jordan, Reid	970-563-4000	maralextechjr@gmail.com	Ignacio
Pesicka, Conor		conor.pesicka@state.co.us	
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	SI	06/12/1983	GW	077-08410	FEDERAL 25-3	TA

General Comment:**COGCC Inspection Report Summary**

On Wednesday 3/25/20 at approximately 15:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S98W /25SESW, Location #312507 in Mesa County Colorado.

Refer to document #696600427 inspection conducted on 8/1/19. Not all previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Access road has not been maintained. See photo #0835 with a corrective action date of 4/25/20. Multiple flow line risers not LO/TO. See photo #0837, #0838, #0839 and #0840 with a corrective action date of 3/26/20. Multiple places with debris on location. See photo #0841 with a previous corrective action date of 8/10/19. MIT required on well. With a corrective action date of 4/25/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:	Access road has not been maintained. See photo #0835			
Corrective Action	Repair and maintain lease road.			Date: 04/25/2020
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Multiple places with debris on location. See photo #0841			
Corrective Action:	Production facilities, shall be kept free of rubbish. Remove all debris from location.			Date: 08/10/2019
Type	UNUSED EQUIPMENT			
Comment:	Multiple flow line risers not LO/TO. See photo #0837, #0838, #0839 and #0840			
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out and tag out risers.			Date: 03/26/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Pipe rail fence			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 221808 Type: WELL API Number: 077-08410 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well last produced prior to January 1999. No MIT on record.Corrective Action: A mechanical integrity test shall be performed on each shut-in well within two years of the initial shut-in date. Preform MIT on well.Date: 04/25/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Gravel						
Ditches						
		Ditches				
		Compaction				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699800787	Photos for Insp. #699800786	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105291