

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/26/2020

Document Number:

693200583

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Murray, Richard 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 13980

Name of Operator: RED ROCK GATHERING COMPANY LLC

Address: 999 18TH STREET STE 3400 SOUTH

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harold Rhodes		harold.rhodes@summitmidstream.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Heil, John		john.heil@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474138	SPILL OR RELEASE	AC	03/26/2020		-	RedRock Gathering System_Premier 6"	EG

**General Comment:**

COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on February 25, 2020. In response to Form 19 Document number 402350573

RedRock Gathering System\_Premier 6" used for LARAMIE ENERGY LLC

BLM surface

**Inspected Facilities**Facility ID: 474138 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Sales Line	1 of Lines	
----	------------------	------------	--

Flowline Description

Flowline Type: Sales Line Size: 6" Material: Carbon Steel  
 Variance: Age: 20+ Yrs Contents: Natural Gas

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No  
 Coatings: Yes External H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: In Process Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: At time of inspection, operator exposed flowline and found ½" hole in the 6 o'clock position

No form 12 or form 44 found for RedRock Gathering System\_Premier 6"

Corrective Action: Provide form 12 or 44 Document numbers showing RedRock Gathering System\_Premier 6" gathering line is registered with COGCC

Provide Root Cause when information becomes available. Via FIRR and email to Western Integrity inspector

Date: 04/15/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200584	Area photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106321">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106321</a>
693200585	6"gathering line	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106322">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106322</a>