

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2020

Submitted Date:

03/20/2020

Document Number:

688307359**FIELD INSPECTION FORM**Loc ID 317368 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 20275Name of Operator: CORAL PRODUCTION CORPAddress: 1600 STOUT ST STE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wieger, Jim	(303) 623-3573	JIMWIEGER@QWESTOFFICE.NET	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269686	WELL	PR	04/01/2012	OW	121-10711	CHRISTIANSEN B-5	PR

General Comment:

Reinspection-animal hole where produced water was leaking from was repaired and stained soil at wellhead was cleaned up (see attached photos). The NFPA label on black produced water tank needs reinspection and offsite sediment transport was not fixed but still within the corrective action dates.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	The black 300 bbl produced water tank does not have an NFPA label but the two tanks next to it does. Need to reinspect.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/10/2020

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	269686	Type:	WELL	API Number:	121-10711	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: Sediment was transported off location and formed a deltalike area in the pond. See attached photos.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/08/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402348737	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101661
688307414	Coral Production Christiansen B-5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101648