

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2020

Submitted Date:

03/27/2020

Document Number:

699800805

**FIELD INSPECTION FORM**

Loc ID 334517 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email                                 | Comment |
|-----------------|-------|---------------------------------------|---------|
| , Laramie       |       | cogccnotifications@laramie-energy.com |         |
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 290711      | WELL | PR     | 08/01/2019  | LO         | 077-09306 | Hells Gulch Federal 35-01W | PR          |

**General Comment:**

**COGCC Inspection Report Summary**  
On Friday 3/27/20 at approximately 14:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Hells Gulch Federal /26-11, Location #334517 in Mesa County Colorado.  
While there, I observed normal production operations.  
During this inspection the following possible compliance issues were observed: Multiple places with unused equipment on location. See photo #0858, #0859, #0860, #0861 and #0862 with a corrective action date of 4/27/20. Flow line risers not LO/TO. See photo #0863 with a corrective action date of 3/28/20.  
  
A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

| Location   |  |        |                         |
|--|--|--------|-------------------------|
| <b>Lease Road:</b>                                     |  |        |                         |
| Type   | Access   |        |                         |
| comment:   |  |        |                         |
| Corrective Action                                      |  |        | Date:                   |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                         |
| <b>Signs/Marker:</b>                                   |  |        |                         |
| Type   | WELLHEAD   |        |                         |
| Comment:   |  |        |                         |
| Corrective Action:                                     |  |        | Date:                   |
| Type   | BATTERY  |        |                         |
| Comment:   |  |        |                         |
| Corrective Action:                                     |  |        | Date:                   |
| Type   | TANK LABELS/PLACARDS   |        |                         |
| Comment:   |  |        |                         |
| Corrective Action:                                     |  |        | Date:                   |
| <b>Emergency Contact Number:</b>                       |  |        |                         |
| Comment:   | <input type="text" value="911"/>   |        |                         |
| Corrective Action:                                     | <input type="text"/>   |        | Date: _____             |
| <b>Good Housekeeping:</b>                              |  |        |                         |
| Type   | UNUSED EQUIPMENT   |        |                         |
| Comment:   | Flow line risers not LO/TO. See photo #0863  |        |                         |
| Corrective Action:                                     | Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out tag out or plug flow line riser.   |        | Date: <u>03/28/2020</u> |
| Type   | STORAGE OF SUPL  |        |                         |
| Comment:   | Multiple places with unused equipment on location. See photo #0858, #0859, #0860, #0861 and #0862  |        |                         |
| Corrective Action:                                     | production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove all unused equipment and supplies from location. |        | Date: <u>04/27/2020</u> |
| Overall Good: <input type="checkbox"/>                 |  |        |                         |
| <b>Spills:</b>   |  |        |                         |
| Type   | Area   | Volume |                         |
| In Containment: No                                     |  |        |                         |
| Comment:   | <input type="text"/>   |        |                         |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                         |
| <b>Equipment:</b>                                      |  |        |                         |
| Type: Horizontal Heated Separator                      | # 1  |        | corrective date         |
| Comment:   |  |        |                         |
| Corrective Action:                                     |  |        | Date:                   |
| Type: Plunger Lift                                     | # 1  |        |                         |
| Comment:   |  |        |                         |

|                               |     |       |  |
|-------------------------------|-----|-------|--|
| Corrective Action:            |     | Date: |  |
| Type: Emission Control Device | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |
| Type: Bird Protectors         | # 1 |       |  |
| Comment:                      |     |       |  |
| Corrective Action:            |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 400 BBLs | STEEL AST |         |        |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                    |  |
|--------------------|--|
| Condition Adequate |  |
| Other (Content)    |  |
| Other (Capacity)   |  |
| Other (Type)       |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |                   |
|--------------------|-------------------|
| Type               | Ignitor/Combustor |
| Comment:           |                   |
| Corrective Action: | Date:             |

**Inspected Facilities**

Facility ID: 290711 Type: WELL API Number: 077-09306 Status: PR Insp. Status: PR

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 699800806    | Photos for Insp. #699800805 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107493">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107493</a> |