

Inspection Photos

Operator: Hilcorp Energy
API#: 067-09551
Date: 3/24/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the northeastern edge facing southward. Revegetation is progressing with mixed wheatgrasses.



Photo 3. View of erosional channeling and failed wattle within the northeastern corner of the working area.



Photo 4. View of the western project area from the northeastern corner facing southward.



Photo 5. View of reference area, comprised of cultivated field in dormant/fallow condition at this time.