

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

696301624

**FIELD INSPECTION FORM**Loc ID 436165 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
James, Brain		bjames@hpres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436162	WELL	PR	10/01/2018	OW	123-38961	Anschutz State 4-62-2-1721BH2	PR
436163	WELL	PR	10/01/2018	OW	123-38962	Anschutz State 4-62-2-3228BH2	PR
436166	WELL	PR	10/01/2018	OW	123-38963	Anschutz State 4-62-2-1721CH2	PR
436167	WELL	PR	10/01/2018	OW	123-38964	Anschutz State 4-62-2-3228CH2	PR
454605	WELL	PR	02/19/2019	OW	123-46651	RSU Anschutz Fed 4-62-2-1609CS	PR
454606	WELL	PR	12/29/2018	OW	123-46652	RSU Anschutz Fed 4-62-2-3340C	PR
454607	WELL	PR	02/19/2019	OW	123-46653	RSU Anschutz Fed 4-62-2-1609CN	PR
454608	WELL	PR	11/16/2018	OW	123-46654	RSU Anschutz Fed 4-62-2-0108C	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Containment north of Pumping Unit is missing Wildlife netting, see photos		
Corrective Action:	Install or repair Wildlife netting on chemical Containment,	Date:	04/24/2020
Type	OTHER		
Comment:	Unmarked Risers on North side of location, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	03/27/2020
Type	STORAGE OF SUPL		
Comment:	Unused Rods and Wellhead parts at Pumping Units		
Corrective Action:	Comply with Rule 603.f.	Date:	04/24/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 10		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: VRU	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLS	STEEL AST		40.345020,-104.300650
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	436162	Type:	WELL	API Number:	123-38961	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436163	Type:	WELL	API Number:	123-38962	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436166	Type:	WELL	API Number:	123-38963	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	436167	Type:	WELL	API Number:	123-38964	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	454605	Type:	WELL	API Number:	123-46651	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	454606	Type:	WELL	API Number:	123-46652	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	454607	Type:	WELL	API Number:	123-46653	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	454608	Type:	WELL	API Number:	123-46654	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Field Inspection. Unmarked Risers on North side of location. Unused Rods at Pumping Units. Containment missing Wildlife netting.</a>	petrie	03/25/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402352877	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105562">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105562</a>
696301625	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105560</a>