

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/26/2020

Submitted Date:

03/26/2020

Document Number:

699101297**FIELD INSPECTION FORM**
 Loc ID 423167 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423150	WELL	PR	03/14/2012	OW	123-33513	GUTTERSEN 2N-5HZ	PR
423151	WELL	PR	03/14/2012	OW	123-33514	GUTTERSEN 27N-5HZ	PR
423165	WELL	PR	07/01/2018	OW	123-33518	GUTTERSEN 1N-5HZ	PR
467060	Flowline System	AC	08/29/2019		-	T3N R63W	AC

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Unreadable Placard. See attached photos		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/27/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Unused wood post by ECD's need to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 603.f .	Date:	04/27/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused Panel Fence and post around wells need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	04/27/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	

Type	WELLHEAD			
Comment:	Panel			
Corrective Action:			Date:	
Type	TANK BATTERY			
Comment:	Barbwire			
Corrective Action:			Date:	

Equipment:			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 3		
Comment:	Appears to be plumbed to surface.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment: Maintenance Tank. Shares containment with crude oil tanks.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER			,
Comment: Shares containment with crude oil tanks.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,
Comment: Shares containment with crude oil tanks.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	10	300 BBLs	STEEL AST		40.247680,-104.460900		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 423150	Type: WELL	API Number: 123-33513	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 423151	Type: WELL	API Number: 123-33514	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 423165	Type: WELL	API Number: 123-33518	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID: 467060	Type: Flowline	API Number: -	Status: AC	Insp. Status: AC
Producing Well				
Comment: AC				
Corrective Action:				Date:

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 3/26/20 at approximately 1017 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Guttarsen 27N-5HZ of Noble Energy, at Location # 423167 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unreadable Placard. Install sign to comply with Rule 210.d. With a corrective action date of 4/27/20.</p> <p>Unused Panel Fence and post around wells need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 4/27/20.</p> <p>Unused wood post by ECD's need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 4/27/20.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	03/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402353327	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105957
699101298	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105945