

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/26/2020

Document Number:

700400668**FIELD INSPECTION FORM**Loc ID 396942 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 86900Name of Operator: TEXACO EXPLORATION AND PRODUCTION INCAddress: 6001 BOLLINGER CANYON RDCity: SAN RAMON State: DC Zip: 94583**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------|
| Trujillo, Aaron | | aaron.trujillo@state.co.us | |
| Sanford, Anita | | atlx@chevron.com | |
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228612 | WELL | PA | 10/10/1961 | DA | 103-05553 | U P R R 70-32 | PA |

General Comment:[COGCC Inspection Report Summary.](#)[On 3-25-2020 at approximately 15:35, inspector Rick Moran, conducted a routine inspection at Texaco well UPPR 70-32 in Rio Blanco county.](#)[The following compliance issues were observed:](#)[1\) 4 Deadman on location. Photo 1. Complete by 5-25-2020.](#)[Note: Abandon pit on SE edge of location. Photo 3.](#)[A follow up inspection will occur to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 700400668.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

| | | | |
|--------------------|-------------------------------|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | 4 unused deadman on location. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 05/25/2020 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 228612 Type: WELL API Number: 103-05553 Status: PA Insp. Status: PA

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Well plugged in 1954 and 1961.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

| Type: <u>Drilling Pit</u> | Lined: | Pit ID: | Lat: | Long: |
|---------------------------------------|-----------------------------|------------------------------|-----------------------------|-------|
| Reference Point: <input type="text"/> | Other: <input type="text"/> | Length: <input type="text"/> | Width: <input type="text"/> | |

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective

Date: **Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402353141 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105833 |
| 700400669 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105821 |