

NRM 808 Government 2-34
API: 05-103-07413
Inspection: 700400826



40.09401, -108.26711, 5710.4ft, 1°
04/01/2020 04:50:16 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

NRM 808 Government 2-34

API: 05-103-07413

Inspection: 700400826



40.09426, -108.26713, 5713.7ft, 55°

04/01/2020 04:49:00 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Meter building & separator.

NRM 808 Government 2-34
API: 05-103-07413
Inspection: 700400826



40.09388, -108.26745, 5706.3ft, 3°
04/01/2020 04:52:19 PM

NRM 808 Government 2-34
API: 05-103-07413
Inspection: 700400826



40.09434, -108.26711, 5706.7ft, 58°
04/01/2020 04:49:15 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Storm water channel s & holes by meter building.

NRM 808 Government 2-34
API: 05-103-07413
Inspection: 700400826

Photo 7



40.09437, -108.26721, 5697.7ft, 347°

04/01/2020 04:54:30 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Storm water channel coming off location down access road.

NRM 808 Government 2-34

API: 05-103-07413

Inspection: 700400826



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Pit on east side of location.

NRM 808 Government 2-34

API: 05-103-07413

Inspection: 700400826



40.09479, -108.26691, 5671.3ft, 354°

04/01/2020 04:55:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Storm water sediment coming from location located 300' away from location.