

**Inspection Photos**  
**Location Name: Mcelwain #13-17**  
**Location ID: 320470**



**Photo 1 TNK BTRY Stormwater: no BMP's in place during the removal of the facility**



**Photo 2 TNK BTRY sign. Storm water no BMP's in place during the removal of the facility**

**Inspection Photos**  
**Location Name: Mcelwain #13-17**  
**Location ID: 320470**



**Photo 3 loc pic**



**Photo 4 loc pic**



**Inspection Photos**  
**Location Name: Mcelwain #13-17**  
**Location ID: 320470**



**Photo 5 Vehicle tracking off road rightaway Between TBK BTRY and Well head**



**Photo 6 Vehicle tracking out side of well pad in planted area.**

**Inspection Photos**  
**Location Name: Mcelwain #13-17**  
**Location ID: 320470**



**Photo 7 Open excavation around well head no safety fence of storm water BMP's in place.**



**Photo 8 Vehicle tracking off well site in planted area**



**Inspection Photos**  
**Location Name: Mcelwain #13-17**  
**Location ID: 320470**



**Photo 9 Vehicle tracking off well site in planted area well out side of permitted area.**



**Photo 10 Storm water: no BMP's in place in removal of well head.**