



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 2, 2020 2:37:01 PM MDT
Server Receive Date:	Apr 2, 2020 2:37:21 PM MDT
Reference Number:	20200402-18138269967
Location:	3261 Co Rd 514, Ignacio, CO 81137, USA Apr 2, 2020 2:36:15 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 2, 2020
Well Name	MCCOY, ROBERT GAS UNIT B 1
Location Name (Other)	MCCOY,ROBERT GAS UNIT B3
API Number	50670784600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Grading/recontour Erosion Repairs Install Rock Run Down

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed

Cleaned derision ditch.



Completed work description of corrective action 2
 Photo of third corrective action completed



Completed work description of corrective action 3
 Completed work description of corrective action 4
 Additional photos



Completed work description
 Summary of all work completed

Grading and cleaned diversion ditch

Installed rock run down silt bowl
 Built new diversion ditch

Installed rock run downs, graded location,
 Installed rock run downs, graded location, cleaned
 diversion ditch and picked up trash.