

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/25/2020

Submitted Date:

03/27/2020

Document Number:

693700367**FIELD INSPECTION FORM**Loc ID 320460 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Devin Brown		dbrown@petrosharecorp.com	
Meghan Grimes		mgrimes@petrosharecorp.com	
Axelson, John		john.axelson@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Kirschner, Steven		steven.kirschner@state.co.us	
Oakman, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203819	WELL	PA	05/18/2018	GW	001-09379	EHLER 44-4	EI
449320	SPILL OR RELEASE	CL	03/03/2017		-	Oil dump line from separator to tnk Ehler 44-4	EI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: [Sign posted at entrance](#)

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Temporary Chain Link Site Perimeter		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	203819	Type:	WELL	API Number:	001-09379	Status:	PA	Insp. Status:	EI
Facility ID:	449320	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC Environmental followup Inspection to Remediation Project #12779. Operator has backfilled and restored surface contours at the location. Site has not been reseeded. Tracking pad, straw waddles and chain-link temporary fence remain on the location. Operator has not supplied laboratory analytical reports that demonstrate material used for backfill complies with Table 910-1 Concentration Levels. Operator has not supplied documentation that horizontal extents of impacts to soil have been defined to the south east. Operator has not supplied documentation showing that the horizontal extents of impacts to groundwater have been defined to the south and east. One monitoring well within site perimeter is damaged.

Corrective Action: Operator shall repair damaged monitoring well to protect groundwater from surface infiltration.

Operator shall submit a Supplemental Form 27 that includes the following:

1. Documentation, supported by original laboratory analytical reports, that demonstrates the material treated onsite and used for backfill complies with Table 910-1 Concentration Levels;
2. Documentation that specifies whether additional material was removed and remaining native soil left onsite complies with Table 910-1 Concentration Levels, supported by original laboratory analytical reports and waste disposal manifests;
3. A proposed soil boring diagram and sampling program that will demonstrate the backfill material and native soil complies with Table 910-1 Concentration Levels if number 1 and 2 above cannot be met;
4. A proposed monitoring well plan to define the extent of impacts to groundwater in all directions to determine whether groundwater remediation is necessary;
5. A timeframe for implementation.

Form 27 Due Date is April 27, 2020 for the proposed boring programs and all existing analytical data. Waste manifests may be submitted on a later Supplemental Form 27.

Date: 04/27/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402354594	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107088
693700371	Ehler44-4 Site Photos 3-25-2020	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5107084