

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2020

Submitted Date:

04/03/2020

Document Number:

689704500

FIELD INSPECTION FORMLoc ID 335729 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292469	WELL	PR	04/04/2009	GW	045-14728	697-12A 12	PR
293509	WELL	PR	02/28/2009	GW	045-15020	697-12A 25	PR
293510	WELL	PR	05/25/2009	GW	045-15021	697-12A 27	PR
293530	WELL	PR	02/28/2009	GW	045-15034	697-12A 16	PR
293531	WELL	WO	02/27/2013	GW	045-15035	697-12A 14	UN
293532	WELL	PR	04/01/2009	GW	045-15036	697-12A 21	PR
293533	WELL	PR	04/01/2009	GW	045-15037	697-12A 23	PR
299531	WELL	PR	04/01/2009	GW	045-17701	697-12A 14B	PR

General Comment:

This is a summary of inspection report.

The status of well 697-12A #18 showing WO but I saw no well head for it but did see a metal cellar ring that has been backfilled. There is a Form 6 (doc# 1705112) from 2008 that is "in-process" still. It looks like a conductor that was plugged.

On 04/01/2020 at approximately 1500 hours, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC 697-12A-66S97W 12SWNE, at Location # 335729 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Battery sign is not legible.

Tank labels are not updated to reflect current operator.

Install sign to comply with Rule 210.e.

C.A. Date 06/02/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Sign is not legible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	06/02/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Signs are not updated to reflect current operator.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	06/02/2020

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	292469	Type:	WELL	API Number:	045-14728	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293509	Type:	WELL	API Number:	045-15020	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293510	Type:	WELL	API Number:	045-15021	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293530	Type:	WELL	API Number:	045-15034	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293531	Type:	WELL	API Number:	045-15035	Status:	WO	Insp. Status:	UN
Idle Well									
Purpose:	<input type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____						
Comment:	The status showing WO but I saw no well head for it but did see a metal cellar ring that has been backfilled. There is a Form 6 (doc# 1705112) from 2008 that is "in-process" still. It looks like a conductor that was plugged.								
Corrective Action:						Date:			
Facility ID:	293532	Type:	WELL	API Number:	045-15036	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	293533	Type:	WELL	API Number:	045-15037	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	299531	Type:	WELL	API Number:	045-17701	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
Berms	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704501	Inspection 689704500 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5114379