

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/24/2020

Submitted Date:

03/29/2020

Document Number:

688307448

FIELD INSPECTION FORM

Loc ID 317368 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 20275
Name of Operator: CORAL PRODUCTION CORP
Address: 1600 STOUT ST STE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Wieger, Jim	(303) 623-3573	JIMWIEGER@QWESTOFFICE.NET	
Chonka, Jim	(303) 623-3573	jpchonka@netscape.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269686	WELL	PR	04/01/2012	OW	121-10711	CHRISTIANSEN B-5	PR

General Comment:

Reinspection, tank label passed, sediment transport corrective action is not yet completed/not past corrective action date.

Inspected Facilities

Facility ID: 269686 Type: WELL API Number: 121-10711 Status: PR Insp. Status: PR

Producing Well

Comment: PR.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: Sediment was transported off location and formed a deltalike area in the pond. See attached photos in previous inspection.

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 04/08/2020

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard:

Comment: Animal holes were repaired and produced water is now going into fiberglass tank at south end of pit, through a pipe and into the pond below the pit.

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402355625	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5108867
688307526	Coral Production Christiansen B-5	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5108845