

Inspection Photos
Operator: Hilcorp Energy
API#: 067-08716
Date: 4/3/2020



Photo 1. View of the project area from the southeastern corner facing center.




Photo 2. View of the western fill slope from the northwestern corner facing southward. Vegetation is largely comprised of dense kochia debris and cheatgrass.



Photo 3. View of dense kochia weed debris along the access road.




Photo 4. View of the eastern project area facing northward from the southeastern corner. An irrigation ditch runs adjacent to the eastern edge and is vegetated with willows. Vegetation above the ditch is largely kochia and other weeds.



Photo 5. View of reference area vegetation comprised of sagebrush shrubland and pinyon juniper woodland.