

**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



**Photo 1 loc pic**



**Photo 2 Dacono 2 WH**

**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



**Photo 3 Dacono #1 WH**



**Photo 4 Dacono #3 WH**



**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



**Photo 5 Crude oil production tank Multiple areas of rust and not painted.**



**Photo 6 loc pic**

**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



Colorado Oil and Gas Conservation Commission  
40.08331, -104.94325, 1521.8m  
Apr 6, 2020 09:26:43

**Photo 7 Improper storage of chemicals in storage building no secondary containment.**



Colorado Oil and Gas Conservation Commission  
40.08333, -104.94326, 1515.3m  
Apr 6, 2020 09:27:33

**Photo 8 Improper storage of chemicals fluid in container almost ready to overflow.**



**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



**Photo 9 Stained soil around compressor in compressor building.**



**Photo 10 Meter house**

**Inspection Photos**  
**Location Name: Dacono 1,2,3**  
**Location ID: 311311**



**Photo 11 inlet to meter house LOTO**



**Photo 12 Outlet from meter house LOTO**