

Inspection Photos

Location Name: Anschutz Equus Farms 3-62-33 NWNW

Location ID: 437854



Photo 1 – Separators




Photo 2 – Wellheads



Inspection Photos

Location Name: Anschutz Equus Farms 3-62-33 NWNW

Location ID: 437854



Photo 3 – Unused Pipe on Southside of Location



Photo 4 – Unused Tarps on Southside of Location



Inspection Photos
Location Name: Anschutz Equus Farms 3-62-33 NWNW
Location ID: 437854



Photo 5 – Unmarked Riser




Photo 6 – Unmarked Risers



Inspection Photos

Location Name: Anschutz Equus Farms 3-62-33 NWNW

Location ID: 437854




Photo 7 – Wildlife netting is in disrepair