

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2020

Submitted Date:

04/07/2020

Document Number:

696201144

**FIELD INSPECTION FORM**

Loc ID 383264 Inspector Name: Trujillo, Aaron On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccnotifications@laramie-energy.com	All inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383264	LOCATION	AC			-	CC 0610-21-41 Pad	CI

**General Comment:**

On 4/7/2020, Reclamation Specialist Trujillo conducted a pre-drill stormwater and construction inspection at Laramie Energy LLC's CC /0610-21-41 Pad location in Garfield County, Colorado.

This inspection is a follow up to inspection #692401319 to document compliance for the following corrective actions: 1002.f: Install or repair required BMPs.

It was documented that perimeter stormwater BMPs appear to have been installed along the perimeter of the Location, and appear to be in proper functioning condition; Stabilization controls appear to have been installed on the fill slopes. BMPs to protect topsoil stockpiles have not been installed per Rule 1002.f and 1002.c.

Refer to the "Location Construction" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location Construction**

Location ID: 383264 CDP: \_\_\_\_\_

Comment: No drilling activities have been conducted on Location; Permits expire 2021. If no drilling activities have been conducted prior to expiration of permits, Location will be subject to 1004.a Final Reclamation.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
SILT FENCES	Yes		

Comments: Erosion BMPs: **Inspection #692401319 observed that the silt fence installed on the perimeter of the Location has not been properly installed. Inspection required Operator to comply with Rule 1002.f.**

**It was observed in this inspection that the BMP appears to have been installed in accordance with good engineering practices, and appears to be in proper functioning condition.**

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

DITCHES	Yes		

Comments: Erosion BMPs: **Inspection #692401319 observed that the ditch installed on the perimeter of the Location has not been properly installed. Inspection required Operator to comply with Rule 1002.f.**

**It was observed in this inspection that the BMP appears to have been installed in accordance with good engineering practices, and appears to be in proper functioning condition.**

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** **Inspection #692401319 observed that the topsoil stockpiles have not been protected in accordance with 1002.f and 1002.c**

**It was observed in this inspection that mulch has been installed as a stabilization control along the fill slopes of the Location. However, BMPs to stabilize and protect the soil stockpiles on the north and east ends of the Location have not been installed in accordance with the corrective action and Rule 1002.f. This corrective action remains applicable.**

**Corrective Action:** **Install or repair required BMPs per Rule 1002.f for protection and segregation of Topsoil.** **Date:** 09/11/2019

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 383264 Type: LOCATION API Number: - Status: AC Insp. Status: CI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696201145	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117563</a>