

Inspection Photos

API: 071-07186

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/6/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020

Inspection Photos



Photo 1. There is soil sloughing that occurred at the east side of the location. Corrective action of the previous inspection was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020

Inspection Photos



Photo 2. Facing toward location. Well sign is posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020

Inspection Photos



Photo 3. There is oil on the engine skid that will need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020

Inspection Photos



Photo 4. Facing down toward the fill slope. There were numerous noxious weeds observed along the fill slope during previous inspection which remain. (Canada thistle, Bull thistle. Noxious weed control will need to be performed in upcoming growing season.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020

Inspection Photos



Photo 5. Facing southwest toward the fill slope. There is an erosion channel that has developed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07186 | Date: 4/6/2020