

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/07/2020

Submitted Date:

04/08/2020

Document Number:

696102683

FIELD INSPECTION FORM

Loc ID: 332245 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Cowan, Peter		picowan@blm.gov	BLM; federal/federal-fee inspections
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271357	WELL	PA	10/12/2018	GW	123-22030	PERKINS 21-22	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Abandoned. ALL equipment has been removed.
Reclamation progressing.
Abandoned Battery SE corner GPS coordinates: 40.386703, -104.419628

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Horizontal Heated Separator	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:
Type: Plunger Lift	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:
Type: Emission Control Device	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:
Type: Pig Station	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:
Type: Gas Meter Run	# 0			
Comment:	Plugged & Abandoned PA. ALL Equipment removed.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 271357 Type: WELL API Number: 123-22030 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 04/07/2020 at approximately 14:22 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte Federal /31-22 Location ID: 332245 Well Name: Perkins 21-22 API: 05-123-22030 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Reclamation progressing. Abandoned Battery SE corner GPS coordinates: 40.386703, -104.419628</p> <p>Comment: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401835326 indicates plugging, cut/cap date: 10/12/2018. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102684	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5118230