

NEW ELK 25-16 API# 05-071-09237 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MARCH 24, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901933



PHOTO 1: THE PACKINGS ON THE WELL HEAD WERE REPLACED TO ELIMINATE THE WATER LEAK. THE SOIL UNDER THE WELL HEAD WAS CLEANED UP.

NEW ELK 25-16 API# 05-071-09237 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 06, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901933



PHOTO 2: THE OIL LEAK ON THE ENGINE SKID WAS REPAIRED. THE OIL ACCUMULATION ON THE ENGINE SKID WAS REMOVED AND THE SKID WAS CLEANED.

NEW ELK 25-16 API# 05-071-09237 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 03, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901933



PHOTO 3: THE IMPACTED SOIL NEXT TO THE ENGINE SKID WAS REMOVED FROM THE LOCATION.

NEW ELK 25-16 API# 05-071-09237 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 03, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901933



PHOTO 4: THE SIDE OF THE TANK WAS CLEANED AND THE LID WAS CLOSED.

NEW ELK 25-16 API# 05-071-09237 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 03, 2020  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901933



PHOTO 5: THE OIL ACCUMULATION ON THE SKID WAS REMOVED AND THE SOIL/GRAVEL WAS CLEANED UP.