

**Inspection Photos**  
**Location Name: UPRR 43 Pan AM 1 #16**  
**Location ID:318369**



**Photo 1 Well head**



**Photo 2 Electric pipe with exposed wires not marked not LOTO.**

**Inspection Photos**  
**Location Name: UPRR 43 Pan AM 1 #16**  
**Location ID:318369**



**Photo 3 Debris/trash: dead weeds around electric panel and on edge of location.**