

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/09/2020

Document Number:

693502653**FIELD INSPECTION FORM**Loc ID 318299 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241061	WELL	PR	04/01/2012	OW	123-08849	LAURIDSON 31-24	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Electric cable with exposed wires not marked and not LOTO		
Corrective Action:	24hrs to LOTO 30 Days to remove. Comply with rule 603 f		Date: <u>05/09/2020</u>
Type	DEBRIS		
Comment:	Dead weeds on site and around electric panel		
Corrective Action:	Comply with rule 603 f		Date: <u>04/16/2020</u>

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Barb wire		
Corrective Action:			Date:

<b>Equipment:</b>				corrective date
Type: Ancillary equipment	# 1			
Comment:	Electric panel			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Gas powered motor			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

--	--	--	--

**Inspected Facilities**

Facility ID: 241061 Type: WELL API Number: 123-08849 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday April 9, 2020 at approximately 9:00 AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Lauridson #31-24</p> <p>Operator: KP Kauffman</p> <p>API#:05-123-08849</p> <p>County: Weld</p> <p>While there, I observed Well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Trash/Debris: Rule 603 f Corrective action date of 4-16-20 See Photos 2,4</p> <p>Unused equipment: Rule 603 f Corrective action date of 5-9-20 See Photo 3</p> <p>Weather conditions: sunny and site dry.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	04/09/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502654	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119464">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119464</a>