

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	TRASH		
Comment:	Old fittings on south edge of location and concrete pad next to guy line anchor. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/11/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused guy line anchors at NW and south edge of location. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/11/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line	# 2		corrective date
Comment:	Improper abandonment of flowline or crude oil transfer line (not purged, depressurized, risers cut 3' below grade, ends sealed, equipment removed) per 1105. Disconnected flowline risers not LOTO. Form 44 notice of abandonment not filed within 30 days. Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216861 Type: WELL API Number: 069-06048 Status: SI Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000992	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5120121