

Inspection Photos
Operator: BP America
API#: 067-08812
Date: 4/8/2020



Photo 1. View of the project area from the well pad entrance facing center.




Photo 2. View of the western fill slope from the southwestern corner facing northward. Vegetation is progressing with a mixture of grasses such as western wheatgrass, squirreltail, and sand dropseed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of erosional channel (approx. 1 foot wide and deep) at culvert outlet (facing downslope), forming around cobble. Cobble is not an adequate BMP.



Musk thistles
from previous
growing season

04.08.2020

Photo 5. View of the southern project area from the southeastern corner facing westward.



Musk thistle from previous growing season, produced numerous seeds.

04.08.2020

Photo 6. View of the southern project area from the southeastern corner facing westward.



Photo 7. View of reference area vegetation, comprised of sagebrush shrubland, with scattered pinyon and juniper trees, and understory of grasses and forbs such as blue grama and sand dropseed.