

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/06/2020

Submitted Date:

04/06/2020

Document Number:

699301359

FIELD INSPECTION FORM

Loc ID 318072 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	All Inspections
,		dnr_cogccenforcement@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240554	WELL	SI	09/01/2018	OW	123-08342	CUYKENDALL 12	SI

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No capacity on crude oil tank		
Corrective Action:	Comply with Rule 210.d. This is being referred to Enforcement; therefore, there is no corrective action date.	Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds and trash scattered throughout location and in PU motor house		
Corrective Action:	Comply with Rule 603.f. This is being referred to Enforcement; therefore, there is no corrective action date.	Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	shares fencing with pumpjack		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Shares fencing with ignitor/combustor		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		

Comment: Barbwire		
Corrective Action:		Date:

Equipment:		corrective date
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: exposed at surface		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Gas engine		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containment with crude tank			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	STEEL AST	
Comment:			
Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Earth	Adequate	Walls Sufficient	Adequate
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240554 Type: WELL API Number: 123-08342 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 4/6/2020 at approximately 1100hrs. I, Inspector Robbie Revas conducted an onsite inspection at a Smith Energy Corp location, Cuykendall 12 @ API# 123-08342 in Weld County Colorado. While there, I observed Shut in well & tank battery. This is a follow up inspection from document # 699300576, 688400338 and 685100948. During this inspection the following Corrective Actions from previous inspections are delinquent: 603.f Housekeeping: Dead weeds around sep, tnk btry, and wh. Trash and unused oil containers inside pumping unit house, buckets and yellow lid around location, stained soil at various spots around location. 210.b: No capacity sign on oil tank. Thief hatch appears to be open to atmosphere. This is being referred to Enforcement; therefore, there is no corrective action date. See attached photos. Submitting this inspection to enforcement due to compliance issues not being addressed. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	revasr	04/06/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402363466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116477
699301360	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116472