

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/31/2020

Submitted Date:

04/06/2020

Document Number:

699700120

**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 Heil, John \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 5201 TRUXTUN AVENUE #100

City: BAKERSFIELD State: CA Zip: 90339

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Wilbourn, Don		dwilbourn@bry.com	
Fischer, Alex		alex.fischer@state.co.us	
Hughes, Jim		jimo.hughes@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
474500	SPILL OR RELEASE	AC	03/31/2020		-	Long Ridge J15	EI

**General Comment:**

On March 31, 2020 and April 1, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of BERRY PETROLEUM COMPANY LLC (Berry operator #10091) Long Ridge J15 Spill/Release Point ID 474500. Berry personnel Don Wilbourn was also on location at time of inspection.



**Environmental****Spills/Releases:**Type of Spill: CONDENSATE

Estimated Spill Volume: \_\_\_\_\_

Comment: 3/30/2020 Operator personnel observed a "mist" coming from the ground at a pipeline right away just south of the J15 location ID 335568 (Doc #402356758). 3/31/2020 COGCC staff observed an excavation approximately 100 feet south of the J 15 location. Hydrocarbon staining and odors were observed where the fluid from the pipeline daylighted at the ground surface. 4/1/2020 A 10-inch and 8-inch pipeline were visible in the excavation south of the J15 location. Both pipelines are located approximately 5 feet below ground surface. The southern pipeline is a 10-inch three phase line and the northern pipeline is a 8-inch water line. Hydrocarbon odor was present at time of inspection around the excavation and stockpiled soil. Operator attempted to relocate impacted material to the J15 location but seized operations due to muddy conditions. See attached photos for details.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.Date: 05/06/2020Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402363377	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116377</a>
699700121	20200331 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116374">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116374</a>