



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE COMING FROM OIL RUNNING OFF PUMPJACK BASE. PHOTO 6: AREA OF IMPACTED SOIL NEAR PUMPJACK PRIME MOVER APPEARS TO BE COMING FROM OIL PUMPJACK PRIME MOVER LEAKS. PHOTO 7: AREA OF IMPACTED SOIL NEAR PUMPJACK PRIME MOVER ON THE OPPOSITE SIDE FROM PREVIOUS PHOTOS APPEARS TO BE COMING FROM OIL PUMPJACK PRIME MOVER LEAKS.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. PER RULE 1002.f.(2).D	Date:	05/06/2020
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED 1" RISER NOT LO/TO.		
Corrective Action:	24 HOURS TO LO/TO 30 DAYS TO REMOVE RISER PER RULE 603.f.	Date:	04/07/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	PHOTO 8: PUMPJACK PRIME MOVER IS SATURATED WITH WHAT APPEARS TO BE OIL.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	05/06/2020
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	IS NOT PLUMBED TO SURFACE	
Corrective Action:		Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 217701 Type: WELL API Number: 071-06480 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402363773	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116821">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116821</a>
695102516	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116819</a>