



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Chainlink topped with barbwire		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 2		corrective date
Comment:	Exposed at surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203 Type: WELL API Number: 123-25431 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 320 Type: WELL API Number: 123-25449 Status: SI Insp. Status: PA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 4/14/2020 at approximately 1015 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Stromquist 23-21 &amp; 35-21 at                      Location #336292 in Weld County Colorado.                      While there, I observed a PA wellsite and a TA wellsite                      Stromquist 23-21 Form 42 Doc # 402344042 submitted on 3-16-2020 approved.                          Form 6 Doc # 402149125 submitted on 8-19-2019 approved.                          Form 17 Doc # 402162650 submitted on 8-30-2019 approved.                      Stromquist 35-21 Form 42 Doc # 401342767 submitted on 7-14-2017 approved.                          Form 6 Doc # 402149128 submitted on 8-19-2019 approved.                          Form 17 Doc # 402162625 submitted on 8-30-2019 approved.</p> <p>During this inspection no compliance issues were observed:                      See attached photos.                      Location is muddy, weather is clear.                      No follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	04/14/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301431	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5124093</a>