

Inspection Photos  
Location Name: Cleveland 2  
Location ID: 332884



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Cleveland 2  
Location ID: 332884



Photo 3 TB sign

Photo 4 TB

Inspection Photos  
Location Name: Cleveland 2  
Location ID: 332884



Photo 5 Vertical heated separator




Photo 6 Stained soil around flow line, possible leak at hammer union.