

**Inspection Photos**  
**Operator: Enduring Resources**  
**API#: 067-07841**  
**Date: 4/14/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Dense jointed goatgrass present on fill slope. Revegetation is progressing in portions of the interim reclamation area that are not infested with jointed goatgrass.



Photo 3. Closeup view of jointed goatgrass from previous year's growing season. Jointed goatgrass is an annual, spring blooming, noxious weed.



Photo 4. View of erosional channel flowing off of the access road, that is not stabilized. Approximately 2-3 feet wide, and deep.



Photo 5. View of another erosional channel flowing off of the access road, that is not stabilized. Approximately 3-4 feet wide and deep.



Photo 6. View of rutting and sedimentation on the access road, approximately 1.5 feet deep.



Photo 7. View of reference area, comprised of pinyon-juniper woodland with understory of gambel oak and mountain mahogany with grasses such as Arizona fescue.